

CATERPILLAR CC24


Description

Caterpillar CC24, Caterpillar , C1.5, 24.6 kW, 9.5/65-15, 4 wheels on rear axle, CE, Erops cabin, Water sprinkler system, Backup alarm, In very good and clean condition.



| | |
|---------------|-------------------|
| Year | 2012 |
| Hours | 4730 |
| Weight | 2700 kg |
| Serial number | CAT0CC24V24100298 |
| Reference | 209522 |

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

| | | | | |
|------------------------|--------------------|---------------|---------------|---------------|
| New/Excellent ★★★★★ | Very good ★★★★☆ | Good ★★★☆☆ | Fair ★★★☆☆ | Poor ★☆☆☆☆ |
|------------------------|--------------------|---------------|---------------|---------------|



INSPECTION REPORT

FEATURES

| | |
|--------------------|-------------|
| Engine brand | Caterpillar |
| Engine model | C1.5 |
| Engine power in kW | 24.6 kW |
| CE | ✓ |

DOCUMENTS

| | |
|------------------|---|
| Parts book | ✓ |
| Operation manual | ✓ |

GENERAL APPEARANCE

| | |
|-------------------------------|-------|
| Stamped serial number checked | Yes |
| Paint | ★★★★☆ |
| Decals | ★★★★☆ |
| Bonnet | ★★★★☆ |

ENGINE DETAILS AND CONDITION

| | |
|-----------------------------|----------|
| Engine number | CMY03094 |
| Air cleaner | Clean |
| Anti-freeze level °C | -44°C |
| Diesel anti-freeze added | Yes |
| Diesel level ok | Yes |
| Cooling liquid level ok | Yes |
| Engine oil level ok | Yes |
| Exhaust manifold | ★★★★☆ |
| Muffler | ★★★★☆ |
| Exhaust stack | ★★★★☆ |
| Hoses | ★★★★☆ |
| Good cold start | Yes |
| Engine power | ★★★★☆ |
| Blow by | ★★★★☆ |
| Knocking | No |
| Compression in the radiator | No |
| Water in the oil | No |
| Oil in the water | No |
| Smoke | Normal |

| | |
|-------------------|-------|
| Engine leaks | No |
| Belts and pulleys | ★★★★☆ |
| Fan | ★★★★☆ |
| Radiator | ★★★★☆ |

SAFETY ITEMS

| | |
|---------------|-------------|
| Backup alarm | Not Working |
| Seat belt | Available |
| Horn | Working |
| Parking brake | Working |

OPERATOR STATION

| | |
|-----------|-----------------------|
| Hourmeter | Working |
| Gauges | Working |
| Switches | ★★★★☆ |
| Warnings | No Warnings Available |
| Seat | ★★★★☆ |

DRUM

| | |
|------------------|--------------------------------------|
| Vibratory system | ★★★★☆ |
| Drum surface | ★★★★☆ |
| Rubber mounts | ★★★★☆ |
| Drum scrapers | ★★★★☆ |
| Travel motors | ★★★★☆ |
| Vibration | Only low vibration frequency working |

STEERING

| | |
|-----------------------------|-------|
| Articulate cylinder leaking | No |
| Play articulating point | ★★★★☆ |
| Steering cylinders leaking | No |
| Play steering cylinders | ★★★★☆ |

HYDRAULICS

| | |
|------------------------------------|-------|
| Hydraulic level ok | Yes |
| Hydraulic lines and fittings | ★★★★☆ |
| Hydraulic tank/sight glass and cap | ★★★★☆ |
| Noise hydraulic pump normal | Yes |
| Operating condition hydraulics | ★★★★☆ |

ELECTRICAL, STARTING AND CHARGING SYSTEM

| | |
|--------------------------------|-------|
| Alternator functioning | Yes |
| Wiring | ★★★★☆ |
| Batteries | ★★★★★ |
| Starter | ★★★★☆ |
| Cabin lights working | Yes |
| Tail lights | Yes |
| Additional work lights working | Yes |

| | | | | |
|------------------------|--------------------|---------------|---------------|---------------|
| New/Excellent ★★★★★ | Very good ★★★★☆ | Good ★★★☆☆ | Fair ★★★☆☆ | Poor ★★★☆☆ |
|------------------------|--------------------|---------------|---------------|---------------|

Copyright Smitma BV

