

BOMAG BW174AP-4I AM

Description

Bomag BW 174 AP-4i AM, Kubota, V3800-CR-T-EF02, 74 kW, Width of the drum 1.68m, EPA, CE, Erops cabin, Water sprinkler system, Drum drive, Both drum vibrating, Compaction frequency variable controllable , Splitted drum, Cutting edge, Chip spreader, Moveable seat, Compaction meter, Frequency meter, Speed meter, In very good and very clean condition.



Year	2014
Hours	3653
Weight	10.885 kg
Serial number	101870751021
Reference	211277



[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine brand	Kubota
Engine model	V3800-CR-T-EF02
Engine power in kW	74 kW
EPA	✓
CE	✓

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆☆
Decals	★★★★☆☆
Engine cover doors	★★★★☆☆
Steps/ladders	★★★★☆☆
Cabin	★★★★☆☆

ENGINE DETAILS AND CONDITION

EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-41°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆
Knocking	No

Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★☆
Radiator	★★★★☆

SAFETY ITEMS

Seat belt	Available
Horn	Working

OPERATOR STATION

Hourmeter	Working
Heater	Not Working
Gauges	Working
Switches	★★★★☆
Display	★★★★☆
Warning	No Warnings Available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★☆
Interior roof	★★★★☆
Seat	★★★★☆
Door lock	Working

FRONT DRUM

Vibratory system	★★★★☆
Drum surface	★★★★☆
Rubber mounts	★★★★☆
Drum scrapers	★★★★☆
Travel motors	★★★★☆
Vibration	High and low vibration frequency working

REAR DRUM

Vibratory system	★★★★☆
Drum surface	★★★★☆

Rubber mounts	★★★★★
Drum scrapers	★★★★★
Travel motors	★★★★★
Vibration	High and low vibration frequency working

STEERING

Steering cylinders leaking	No
Play steering cylinders	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional lights working	Yes

New/Excellent



Very good



Good



Fair



Poor

