

CATERPILLAR 323 07B | 70% GOOD U/C

Description


Caterpillar 323 07B, Engine brand and model Caterpillar C7.1, 122 kW, EPA, CE, Air conditioning, Central lubrication, Backup camera, Immobilizer, Cat walk, Integrated grade control, Width of the pads 900mm, Mono boom, Length of the mono boom 5.70m, Length of the stick 2.90m, Hydraulic quick release, Ditch cleaning bucket, Width of the bucket 2.10m, Piped for hammer, shear and clamp, Burst valve on lift and stick cylinder, Hours certified by Caterpillar, In very good and clean condition.



Year	2019
Hours	10050
Weight	22800 kg
Serial number	CAT00323KRAZ10439
Reference	211100

[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840



INSPECTION REPORT

FEATURES

Engine brand and model	Caterpillar C7.1
Engine power in kW	122 kW
EPA	EPA
CE	✓
Air conditioning	✓
Cat walk	✓
Width of the pads	900mm
Boom	Mono boom
Length of the mono boom	5.70m
Length of the stick	2.90m
Bucket	Ditch cleaning bucket
Width of the bucket	2.10m
Piped	Piped for hammer, shear and clamp
Hours	Hours certified by Caterpillar
Overall condition	In very good and clean condition.

DOCUMENTS

CE document	CE document available
Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★☆
Chassis	★★★★★
Bottom plates	★★★★☆
Counter weight	★★★★★
Toolbox	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★

Cabin	★★★★★
Cracks or welds	No

ENGINE DETAILS AND CONDITION

Engine number	D8T47102
Arrangement number	5019662
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-44°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★
Ad blue	✓

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	70% GOOD!
Chains	80%
Bushings	80%
Sprockets	70%
Idlers	70%
Bottom rollers	40%
Top rollers	90%
Track pads	70%

SAFETY ITEMS

Backup camera	Working
Seat belt	Available
Horn	Working

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No

Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BOOM AND STICK

Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play boom pen	★★★★★
Play stick cylinder	★★★★★
Stick cylinder leaking	No
Play stick pen	★★★★★
Note: Little play	
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboom	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Additional work lights working	Yes

