

CATERPILLAR 314E LCR

Description

Caterpillar 314ELCR, Engine brand and model Caterpillar C4.4, 71 kW, EPA, Air conditioning, Central lubrication, Backup camera, Width of the pads 500mm, Mono boom, Length of the mono boom 4.65m, Length of the stick 2.50m, Hydraulic quick release, Digging bucket with teeth, Width of the bucket 1.21m, Piped for hammer, shear and clamp, Burst valve on lift and stick cylinder, Hours certified by Caterpillar, In very good and very clean condition.



Year 2013

Hours 10405

Weight 17.100 kg

Serial number CAT0314ECDKD00231

Reference 204320

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
 ★★★★★

Very good
 ★★★★★★

Good
 ★★★★★★

Fair
 ★★★★★★

Poor
 ★★★★★★



INSPECTION REPORT

FEATURES

Engine brand and model	Caterpillar C4.4
Engine power in kW	71 kW
EPA	EPA
Air conditioning	✓
Width of the pads	500mm
Boom	Mono boom
Length of the mono boom	4.65m
Length of the stick	2.50m
Bucket	Digging bucket with teeth
Width of the bucket	1.21m
Piped	Piped for hammer, shear and clamp
Overall condition	In very good and very clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Bottom plates	★★★★★
Counter weight	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Cracks or welds	No

ENGINE DETAILS AND CONDITION

Engine number	C7N13566
---------------	----------

Arrangement number	345-2884
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-25°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★☆☆☆
Engine supports	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆☆
Fan	★★★★☆☆
Radiator	★★★★☆☆

BUCKET

Overall condition of the bucket	★★★★☆☆
Bottom	★★★☆☆☆
Sides	★★★★☆☆
Teeth	★★★★☆☆

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	70%
Chains	80%
Bushings	90%
Sprockets	60%
Idlers	70%
Bottom rollers	70%

Top rollers	70%
Track pads	30%

SAFETY ITEMS

Backup camera	Working
Seat belt	Available
Horn	Working

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BOOM AND STICK

Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play boom pen	★★★★★
Play stick cylinder	★★★★★
Stick cylinder leaking	No
Play stick pen	★★★★★
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboom	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

