

CATERPILLAR 962H

Description

Caterpillar 962H, Engine and model Caterpillar C7, Air conditioning, Erops cabin, 23.5R25, GP bucket with teeth, Width of the bucket 2.95m, Complete steering wheel, Ride control, Autoshift, Backup camera, Cental lubrication available but not tested, Hours certified by Caterpillar, In good and very clean condition.



Year	2010
Hours	14538
Weight	19.740 kg
Serial number	CAT0962HHN4A02094
Reference	209756

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

Engine and model	Caterpillar C7
Erops cabin	✓
Tyre size	23.5R25
Bucket	GP bucket with teeth
Width of the bucket	2.95m
Steering	Complete steering wheel
Ride control	✓
Autoshift	✓
Central lubrication	Cental lubrication available but not tested
Hours	Hours certified by Caterpillar
Overall condition	In good and very clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★☆☆☆☆
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Pre-cleaner bowl	★★★★★
Toolbox	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	KHX22583
Air cleaner	Clean
Anti-freeze level °C	-47°C
Diesel anti-freeze added	Yes

Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Few don't work
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Teeth	★★★★★

FRAME

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes

Additional work lights working

Yes

SAFETY ITEMS

Seat belt

Available

Horn

Working

TYRES

FRONT LEFT

Tread dept in mm

36mm

Percentage life remaining

50%

REAR LEFT

Tread dept in mm

39mm

Percentage life remaining

60%

REAR RIGHT

Tread dept in mm

37mm

Percentage life remaining

50%

FRONT RIGHT

Tread dept in mm

57mm

Percentage life remaining

80%

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV

