

INSPECTION REPORT

CATERPILLAR 336 07A GC

The Caterpillar 336GC 07A is a versatile and powerful excavator designed for efficiency and comfort on the job site. Equipped with a Caterpillar C7.1 engine, this machine offers 205 kW of power. With features like air conditioning, central lubrication, and a backup camera, it ensures both operator comfort and operational efficiency. The hydraulic quick release and various pipings enhance its adaptability for different attachments, like a digging bucket with teeth. Its robust construction is coupled with thoughtful design elements like cabin protection and immobilizer for safety.



Specifications

Year	2019
Hours	10465
Weight	34.800 kg
Serial number	CAT00336CDWL00184
Reference	210744

Features

Engine brand and model	Caterpillar C7.1
Engine power in kW	205kW
CE	✓
Air conditioning	✓
Cabin protection	✓
Width of the pads	600mm
Boom	Mono boom
Length of the mono boom	6.50m
Length of the stick	2.80m
Bucket	Digging bucket with teeth
Width of the bucket	1.62m
Piped	Piped for hammer, shear and clamp
AM/FM Radio	✓
Hours	Hours certified by Caterpillar
Overall condition	In good and clean condition.

Documents

Parts book	✓
Operation manual	✓

General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Bottom plates	★★★★★
Counter weight	★★★★★
Toolbox	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Central greasing working	Yes
Cracks or welds	No

Engine Details And Condition

Engine number	J7A00360
Air cleaner	Clean
Anti-freeze level °C	-36°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★
Ad blue	✓

Bucket

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Teeth	★★★★★

Undercarriage Left In Life In %

Overall condition	75%
Chains	70%
Bushings	80%
Sprockets	70%
Idlers	80%
Bottom rollers	70%
Top rollers	80%
Track pads	70%

Safety Items

Backup camera	Working
Seat belt	Available

Operator Station

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

Hydraulics

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

Boom And Stick

Play lift cylinder	★ ★ ★ ★ ★	
Lift cylinders leaking		No
Play boom pen	★ ★ ★ ★ ★	
Play stick cylinder	★ ★ ★ ★ ★	
Stick cylinder leaking		No
Play stick pen	★ ★ ★ ★ ★	
Play bucket cylinder	★ ★ ★ ★ ★	
Bucket cylinder leaking		No
Play bucket link	★ ★ ★ ★ ★	
Play bucket pen	★ ★ ★ ★ ★	
Condition monoboom	★ ★ ★ ★ ★	
Condition stick	★ ★ ★ ★ ★	

Swing Circle

Play on the swing bearing	★ ★ ★ ★ ★	
Play on the swing		
Play in mm on the swing bearing		Play on the swing within CAT margin
Swing gear	★ ★ ★ ★ ★	
Swing drive oil level ok		Yes
Swing drive leaking		No
Swing brake operating		Yes
Swing noise normal		Yes
Hydraulic swivel leaking		No
Operating condition	★ ★ ★ ★ ★	

Electrical, Starting And Charging System

Alternator functioning		Yes
Wiring	★ ★ ★ ★ ★	
Batteries	★ ★ ★ ★ ★	
Starter	★ ★ ★ ★ ★	
Cabin lights working		Yes
Additional work lights working		Yes



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)



sales@smitma.com



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)