

CATERPILLAR D8T - CE - NEW RIPPER

Description

Caterpillar D8T, Engine brand Caterpillar , C15, 294 kW, CE, Air conditioning, Erops cabin, Straight tilt blade, Width of the blade 4.01m, Differential steering, Single shank ripper, Hydraulic pin puller, Width of the pads 610mm, Backup camera, AM/FM radio, Hours certified by Caterpillar, In very good and very clean condition.



| | |
|---------------|-------------------|
| Year | 2019 |
| Hours | 12716 |
| Weight | 39.425 kg |
| Serial number | CAT00D8THAW400573 |
| Reference | 205670 |

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

| | |
|--------------------|----------------------------------------|
| Engine brand | Caterpillar |
| Engine model | C15 |
| Engine power in kW | 294 kW |
| CE | ✓ |
| Air conditioning | ✓ |
| Erops cabin | ✓ |
| Blade | Straight tilt blade |
| Width of the blade | 4.01m |
| Steering | Differential steering |
| Ripper or valve | Single shank ripper |
| Width of the pads | 610mm |
| Overall condition | In very good and very clean condition. |

DOCUMENTS

| | |
|------------------|-----------------------|
| CE document | CE document available |
| Parts book | ✓ |
| Operation manual | ✓ |

GENERAL APPEARANCE

| | |
|-------------------------------|-------|
| Stamped serial number checked | Yes |
| Serial number plate checked | Yes |
| Paint | ★★★★☆ |
| Decals | ★★★★☆ |
| Bonnet | ★★★★☆ |
| Engine cover doors | ★★★★☆ |
| Chassis | ★★★★☆ |
| Grab irons | ★★★★☆ |
| Cabin | ★★★★☆ |
| Belly plate | ★★★★☆ |
| Pre-cleaner bowl | ★★★★☆ |

ENGINE DETAILS AND CONDITION

| | |
|--------------------|----------|
| Engine number | ENG04720 |
| Arrangement number | 5504646 |
| Air cleaner | Clean |

| | |
|-----------------------------|--------|
| Anti-freeze level °C | -34°C |
| Diesel anti-freeze added | Yes |
| Diesel level ok | Yes |
| Cooling liquid level ok | Yes |
| Engine oil level ok | Yes |
| Exhaust manifold | ★★★★☆☆ |
| Muffler | ★★★★☆☆ |
| Exhaust stack | ★★★★☆☆ |
| Engine supports | ★★★★☆☆ |
| Hoses | ★★★★☆☆ |
| Good cold start | Yes |
| Engine power | ★★★★☆☆ |
| Blow by | ★★★★☆☆ |
| Knocking | No |
| Compression in the radiator | No |
| Water in the oil | No |
| Oil in the water | No |
| Smoke | Normal |
| Engine leaks | No |
| Belts and pulleys | ★★★★☆☆ |
| Fan | ★★★★☆☆ |
| Radiator | ★★★★☆☆ |

UNDERCARRIAGE LEFT IN LIFE IN %

| | |
|-------------------|-----|
| Overall condition | 50% |
| Chains | 60% |
| Bushings | 60% |
| Sprockets | 60% |
| Idlers | 60% |
| Bottom rollers | 30% |
| Track pads | 40% |

OPERATOR STATION

| | |
|------------------|-----------------------------------------|
| Hourmeter | Working, hours certified by Caterpillar |
| Air conditioning | Working |
| Heater | Working |
| Gauges | Working |
| Switches | ★★★★☆☆ |
| Display | ★★★★☆☆ |

| | |
|-------------------|-----------------------|
| Warning | No Warnings Available |
| Cabin glass | Not broken |
| Windshield wipers | Working |
| Cabin floor | ★★★★★ |
| Interior roof | ★★★★★ |
| Seat | ★★★★★ |
| Door lock | Working |

STEERING

| | |
|------------------------------|-------|
| Steering operating condition | ★★★★★ |
|------------------------------|-------|

FRAME AND BLADE

| | |
|------------------------|-------|
| Moldboard skin | ★★★★★ |
| Cutting edge | ★★★★★ |
| Play dozer frame | ★★★★★ |
| Play blade pin | ★★★★★ |
| Play push arms | ★★★★★ |
| Play lift cylinder | ★★★★★ |
| Lift cylinders leaking | No |
| Play tilt cylinder | ★★★★★ |
| Tilt cylinder leaking | No |
| Play equaliser bar | ★★★★★ |
| Cracks or welds | No |

RIPPER

| | |
|-------------------|-------|
| Play ripper | ★★★★★ |
| Cylinders leaking | No |
| Ripper frame | ★★★★★ |

HYDRAULICS

| | |
|------------------------------------|-------|
| Hydraulic oil level ok | Yes |
| Hydraulic lines and fittings | ★★★★★ |
| Hydraulic tank/sight glass and cap | ★★★★★ |
| Hydraulic valves leaking | No |
| Noise hydraulic pump normal | Yes |
| Operating condition hydraulics | ★★★★★ |

BRAKE

| | |
|-------------------------|-------|
| Service brake operation | ★★★★★ |
|-------------------------|-------|

Parking brake operation



DRIVE TRAIN/TRANSMISSION

| | |
|-----------------------------------------------------------------|-----|
| Transmission fully operational in all gears forward and reverse | Yes |
| Transmission oil level ok | Yes |
| Transmission noisy | No |
| Oil level left final drive ok | Yes |
| Oil level right final drive ok | Yes |
| Drive chain leaks | No |

ELECTRICAL, STARTING AND CHARGING SYSTEM

| | |
|--------------------------------|--------|
| Alternator functioning | Yes |
| Wiring | ★★★★★ |
| Batteries | ★★★★★★ |
| Starter | ★★★★★ |
| Cabin lights working | Yes |
| Additional work lights working | Yes |

SAFETY ITEMS

| | |
|---------------|-----------|
| Backup alarm | Working |
| Backup camera | Working |
| Seat belt | Available |
| Horn | Working |

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV

