

VOLVO DD22

Description

Volvo DD22, Kubota, V2203, 24 kW, Width of the drum 1000mm, EPA, CE, Water sprinkler system, Drum drive, Both drum vibrating, Backup alarm, In good and clean condition.



Year	2010
Hours	2256
Weight	2.450 kg
Serial number	VCE00D22JOH650084
Reference	205277

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

Engine brand	Kubota
Engine model	V2203
Engine power in kW	24 kW
EPA	✓
CE	✓

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆☆
Decals	★★★★☆☆
Bonnet	★★★★☆☆
Steps/ladders	★★★★☆☆

ENGINE DETAILS AND CONDITION

Anti-freeze level °C	-21°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No

Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

SAFETY ITEMS

Backup alarm	Not Working
Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No Warnings Available
Cabin floor	★★★★★
Seat	★★★★★

FRONT DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Travel motors	★★★★★
Left final drive leaking	No
Right final drive leaking	No

REAR DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Travel motors	★★★★★
Left final drive leaking	No
Right final drive leaking	No

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Play articulating point	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Few lights don't work
Tail lights working	No

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

