

BOMAG BW154AP-AM

Description

Bomag 154AP-AM, Kubota , V3307-DI-T-ET04, 55.4 kW, Width of the drum 1.50m, EPA, CE, Erops cabin, Water sprinkler system, Drum drive, Both drum vibrating, Compaction frequency variable controllable , Splitted drum, Cutting edge, Moveable seat, Compaction meter, Frequency meter, Speed meter, Air conditioning, Backup alarm, AM/FM radio, In very good and very clean condition.



Year	2008
Hours	4330
Weight	7300 kg
Serial number	101870601020
Reference	207372

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★☆☆☆☆

Copyright Smitma BV



INSPECTION REPORT

FEATURES

Engine brand	Kubota
Engine model	V3307-DI-T-ET04
Engine power in kW	55.4 kW
EPA	✓
CE	✓

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆☆
Decals	★★★★☆☆
Engine cover doors	★★★★☆☆
Steps/ladders	★★★★☆☆
Cabin	★★★★☆☆

ENGINE DETAILS AND CONDITION

Engine number	8E0403
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-50°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆

Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No Warnings Available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

FRONT DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Travel motors	★★★★★

Vibration

High and low vibration frequency working

REAR DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Travel motors	★★★★★
Vibration	High and low vibration frequency working

STEERING

Play articulating point	★★★★★
Steering cylinders leaking	No
Play steering cylinders	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional lights working	Yes

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

