

CATERPILLAR 336F L

Description

Caterpillar 336FL , Engine brand and model Caterpillar , 236 kW, EPA, CE, Air conditioning, Central lubrication, Backup camera, Width of the pads 600mm, Mono boom, Length of the mono boom 6.50m, Length of the stick 2.80m, Digging bucket with teeth, Width of the bucket 1.57m, Burst valve on lift and stick cylinder, AM/FM Radio, Hours certified by Caterpillar, In very good and clean condition.



Year	2017
Hours	8173
Weight	37.780 kg
Serial number	CAT0336FLKCS10031
Reference	211671



[Download photos](#)

CONTACT US:
 SALES@SMITMA.COM
 +31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine brand and model	Caterpillar
Engine power in kW	236 kW
EPA	EPA
CE	✓
Air conditioning	✓
Width of the pads	600mm
Boom	Mono boom
Length of the mono boom	6.50m
Length of the stick	2.80m
Bucket	Digging bucket with teeth
Width of the bucket	1.57m
AM/FM Radio	✓
Hours	Hours certified by Caterpillar
Overall condition	In very good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★ ★ ★ ★ ★
Body work	★ ★ ★ ★ ★
Decals	★ ★ ★ ★ ★
Bonnet	★ ★ ★ ★ ★
Engine cover doors	★ ★ ★ ★ ★
Chassis	★ ★ ★ ★ ★
Bottom plates	★ ★ ★ ★ ★
Counter weight	★ ★ ★ ★ ★
Toolbox	★ ★ ★ ★ ★
Steps/ladders	★ ★ ★ ★ ★
Grab irons	★ ★ ★ ★ ★
Cabin	★ ★ ★ ★ ★
Pre-cleaner bowl	★ ★ ★ ★ ★

Cracks or welds No

ENGINE DETAILS AND CONDITION

Engine number	SYE15136
Arrangement number	4859800
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-47°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★★☆☆
Engine supports	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆☆
Fan	★★★★☆☆
Radiator	★★★★☆☆
Ad blue	✓

BUCKET

Overall condition of the bucket	★★★★☆☆
Bottom	★★★★☆☆
Sides	★★★★☆☆
Cutting edge	★★★★☆☆
Teeth	★★★★☆☆

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	50%
Chains	40%
Bushings	40%
Sprockets	60%
Idlers	70%
Bottom rollers	30%
Top rollers	80%
Track pads	50%

SAFETY ITEMS

Backup camera	Working
Seat belt	Available
Horn	Working

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Few don't work
Switches	★★★★☆
Display	★★★★☆
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★☆
Interior roof	★★★★☆
Seat	★★★★☆
Door lock	Working

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★☆
Hydraulic tank/sight glass and cap	★★★★☆
Travel motors	★★★★☆
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No

Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BOOM AND STICK

Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play boom pen	★★★★★
Play stick cylinder	★★★★★
Stick cylinder leaking	No
Play stick pen	★★★★★
Note: Little play	
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Note: Little play	
Condition monoboam	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Additional work lights working	Yes

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV