


Avesco Oy, Kiitoradantie 4, 01532, Vantaa

Cat Certified Used 12 months or 1000 hours (whichever is reached first) on powertrain and hydraulic components

<p>Order Number</p> <p>Machine family Medium wheel loaders</p> <p>Brand Caterpillar</p> <p>Type 982</p> <p>Serial N° KL8410118</p> <p>Year 2025</p> <p>Operating hours 5393</p> <p>Engine Cat C13</p> <p>Power hp/kW 301kw</p> <p>Weight (kg) 35600</p> <p>Location Oulu</p> <p>Length (mm) 10018</p> <p>Width (mm) 3490</p> <p>Height (mm) 4110</p>	<table> <tr> <td>ROPS</td> <td>Yes</td> </tr> <tr> <td>Bucket 1(width) (mm)</td> <td>Kauha</td> </tr> <tr> <td>Bucket dimensions, volume, other tools</td> <td>Pienituntinen vuoden vanha kone kauhalla valmis töihin. Renkaat 80%, kauha +50% . Erinomainen vaihtoehto!</td> </tr> <tr> <td>Bucket</td> <td>Blade</td> </tr> <tr> <td>Air-conditioning system</td> <td>Yes</td> </tr> <tr> <td>Particle filter</td> <td>Ex Works, Ready for Use</td> </tr> <tr> <td>Heating</td> <td>Yes</td> </tr> <tr> <td>Lighting</td> <td>Yes</td> </tr> <tr> <td>Central lubrication</td> <td>Yes</td> </tr> <tr> <td>Condition front left</td> <td>80%</td> </tr> <tr> <td>Condition rear left</td> <td>80%</td> </tr> <tr> <td>Condition front right</td> <td>80%</td> </tr> <tr> <td>Condition rear right</td> <td>80%</td> </tr> </table>	ROPS	Yes	Bucket 1(width) (mm)	Kauha	Bucket dimensions, volume, other tools	Pienituntinen vuoden vanha kone kauhalla valmis töihin. Renkaat 80%, kauha +50% . Erinomainen vaihtoehto!	Bucket	Blade	Air-conditioning system	Yes	Particle filter	Ex Works, Ready for Use	Heating	Yes	Lighting	Yes	Central lubrication	Yes	Condition front left	80%	Condition rear left	80%	Condition front right	80%	Condition rear right	80%	 <p>Net price excluding VAT 359,000 EUR</p> <p>Price and technical changes reserved without prior notice</p>
ROPS	Yes																											
Bucket 1(width) (mm)	Kauha																											
Bucket dimensions, volume, other tools	Pienituntinen vuoden vanha kone kauhalla valmis töihin. Renkaat 80%, kauha +50% . Erinomainen vaihtoehto!																											
Bucket	Blade																											
Air-conditioning system	Yes																											
Particle filter	Ex Works, Ready for Use																											
Heating	Yes																											
Lighting	Yes																											
Central lubrication	Yes																											
Condition front left	80%																											
Condition rear left	80%																											
Condition front right	80%																											
Condition rear right	80%																											

[Contact](#)

