

| Evaluation Wheel Excavator | | www.mevas.net |  |
|--------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|------------------------------------------------------|-------------------------------------------------------------------------------------------|
| Customer/Location: | Prima / Hardenberg | vers 12-2024 | |
| Date: | 16.12.2025 | | |
| Machine / type: | Hyundai HW160 | Hour reading: | 9486 |
| Serial No.: | HHKHK501K0000010 | Year: | 2016 |
| Inspector: | B. Hecker | stick length: | 2,50 m |
| CE <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/> | A/C <input checked="" type="checkbox"/> stick check valve <input checked="" type="checkbox"/> | boom check valve <input checked="" type="checkbox"/> | quick coupler <input checked="" type="checkbox"/> DPF <input checked="" type="checkbox"/> |
| mono-boom <input type="checkbox"/> | boom variable <input checked="" type="checkbox"/> | hammer lines <input checked="" type="checkbox"/> | lines for grapple / shear <input checked="" type="checkbox"/> |
| cab | | cab door | good |
| seat, arm rests | good | windows & mirrors | good |
| switches, levers | good | wipers, washer | good |
| gauges & warn lights | good | floor mat & pedals | good |
| aircon / heater | good | cab structure | good |
| engine | | | |
| leaks & seals | leaks on hydraulic pump joint | Serial No. | 22211805 |
| oil condition & level | good | cooling system | good |
| exhaust, muffler | good | blow by | minor |
| smoke | normal | belts & filters | good |
| DPF/DEF status | good | coolant condition | good |
| visual inspection exterior | | counterweight | good |
| chassis & carbody | good | bumpers & covers | good |
| side doors | good | outriggers & blade | good |
| stairs, hand rails | good | lights, batteries | good |
| boom | good | paintwork | small scratches |
| stick | good | rims, wheel nuts | good |
| hydraulics & drive train | | boom cylinders | good |
| hoses & lines | good | stick cylinder | good |
| pump & valve bloc | good | bucket cylinder | good |
| transmission gear | good | outr/blade cylinders | good |
| axles | good | universal joints | good |
| swivel joint | good | | |
| functional test | | suspension lock | good, cylinder rods rusty |
| pins boom | good | pump noises | good |
| pins stick | good | slew ring play | 1,5 mm play |
| pins bucket | good | brake & park brake | good |
| boom self drift | good | electric system | good |
| swing drive/brake | good | drive operation | good |
| tools | | additional bucket | no |
| bucket dimension | 2,1m DC bucket | coupler brand | Verachtert, Hydraulic CW30H |
| bucket condition | good | coupler condition | good |
| tires | mm (%) remaining life | size: | 10.00 - 20 |
| front right | 40% | twin / mono: | twin |
| front left | 40% | spacer rings: | <input checked="" type="checkbox"/> |
| rear right | 40% | damages or cuts: | |
| rear left | 40% | solid: | <input type="checkbox"/> |
| problems, details: | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| dimensions for transport L x W x H in meter: | 8,00 m x 2,50 m x 3,30 m | | |

The machine is in general good condition. Smaller repairs recommended.

dimensions for transport L x W x H in meter: 8,00 m x 2,50 m x 3,30 m