

VOGELE SUPER 1900-3I - INCLUDING EXTENSIONS

Description

Vogele SUPER 1900-3i, Engine brand Cummins , QSB6.7 190, 142 kW, EPA, CE, Track driven, AB 500-3 TP2, 5.00m + 2x 0.75m extensions, Tamping & vibrating function, Electrical heated, Hydraulic side plates, Hydraulic crown adjustment, Vogele level control, 2 grade & 1 slope control, Hard cover roof, Central lubrication, In very good and very clean condition



Year	2014
Hours	11150
Weight	20.900 kg
Serial number	08190204
Reference	204493

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆


INSPECTION REPORT

FEATURES

Engine brand	Cummins
Engine model	QSB6.7 190
Engine power in kW	142 kW
EPA	✓
CE	✓
Track driven	✓
Screed model	AB 500-3 TP2
Width of the screed	5.00m + 2x 0.75m extensions
Screed function	Tamping & vibrating function
Screed heating	Electrical heated
Hydraulic side plates	✓
Hydraulic crown adjustment	✓
Brand high leveling	Vogele level control
Roof	Hard cover roof
Central lubrication	✓
Overall condition	In very good and very clean condition

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Cracks or welds	No

Condition of the hopper plates in mm	9.5mm
Condition of the hopper	★★★★★
Condition of the augers	★★★★★
Condition of the screed plates in mm	7.5mm

ENGINE DETAILS AND CONDITION

Engine number	22089630
Air cleaner	Clean
Anti-freeze level °C	-25°C
Diesel anti-freeze	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	80%
Track pads	60%
Track chains and sprockets	80%

OPERATOR STATION

Hourmeter	Working
Gauges	Working

Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Cabin glass	Not broken
Windshield wipers	Working
Seat	★★★★★

HYDRAULICS

Hydraulic oil level	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

DRIVE TRAIN/TRANSMISSION

Drivetrain leaks	No
------------------	----

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes

SAFETY ITEMS

Backup alarm	Working
Horn	Working
Beacon	Working

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

