

VOLVO A30F

Description

Volvo A30F, Engine Volvo, D11H, 265 kW, CE, Air conditioning, 6x6, Erops cabin, 750/65R25 Bridgestone 75%, Retarder, Heated body, Big tailgate, Body extensions, Backup camera, Backup alarm, AM/FM radio, In very good and clean condition.



Year	2013
Hours	11335
Weight	23.200 kg
Serial number	VCE0A30FH00012453
Reference	211478

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine	Volvo
Engine model	D11H
Engine power	265 kW
CE	✓
Air conditioning	✓
Configuration	6x6
Erops cabin	✓
Retarder	✓
Heated body	✓
Tailgate	Big tailgate
Backup camera	✓
Backup alarm	✓
Overall condition	In very good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Transmission guard	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	285264
Air cleaner	Clean
Anti-freeze level °C	-36°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes

Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

FRAME

Play front suspension frame	★★★★★
Play middle suspension frame	★★★★★

Play rear suspension frame	★★★★★
Play articulation point	★★★★★
Shock absorbers articulation point	★★★★★
Play body tipping pin	★★★★★
Bearings tipping cylinders	★★★★★
Shock absorbers body	★★★★★
Play rear equalizer	★★★★★
Shock absorbers equalizer	★★★★★
Cracks or welds	No

BODY

Condition outside body	★★★★★
Body plates	★★★★★
Body heating system	★★★★★
Condition tailgate	★★★★★
Cracks or welds	No

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★
Brake pedal	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transfer gear box oil level ok	Yes
Transmission noisy	No
Differential lock/unlock working	Yes
Oil level front axle ok	Yes

Oil level middle axle ok	Yes
Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level middle left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level middle right final drive ok	Yes
Oil level front right final drive ok	Yes
Drive chain leaks	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

SAFETY ITEMS

Backup alarm	Not working
Backup camera	Working
Seat belt	Available
Horn	Working

TYRES

FRONT LEFT

Tread dept in mm	34mm
Percentage life remaining	80%

MIDDLE LEFT

Tread dept in mm	31mm
Percentage life remaining	70%

REAR LEFT

Tread dept in mm	33mm
Percentage life remaining	80%

REAR RIGHT

Tread dept in mm	32mm
Percentage life remaining	70%

MIDDLE RIGHT

Tread dept in mm	31mm
Percentage life remaining	70%

FRONT RIGHT

Tread dept in mm	34mm
Percentage life remaining	80%

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★★★☆☆
------------------------	--------------------	---------------	---------------	---------------

