


CATERPILLAR 930M

Description

Caterpillar 930M, Engine and model Caterpillar C7.1, 122 kW, EPA, CE, Air conditioning, Erops cabin, 20.5x25 - 90%, Hydraulic quick release, High tip bucket, Width of the bucket 2.53m, 3rd valve, Complete steering wheel, Ride control, Autoshift, Backup camera, Backup alarm, Cental lubrication available but not tested, Beacon, AM/ FM radio, Hours certified by Caterpillar, In very good and clean condition.



Year	2019
Hours	8861
Weight	13800 kg
Serial number	CAT0930MLKTG05030
Reference	209505

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

Engine and model	Caterpillar C7.1
Engine power	122 kW
EPA	EPA
CE	✓
Erops cabin	✓
Tyre size	20.5x25 - 90%
Bucket	High tip bucket
Width of the bucket	2.53m
Steering	Complete steering wheel
Ride control	✓
Autoshift	✓
Central lubrication	Cental lubrication available but not tested
Beacon	✓
Hours	Hours certified by Caterpillar
Overall condition	In very good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	D8T51589
Arrangement number	5595328

EPA sticker available	Yes
Air cleaner	New
Anti-freeze level °C	-39°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★

Seat	★ ★ ★ ★ ★
Door lock	Working
BUCKET	
Overall condition of the bucket	★ ★ ★ ★ ★
Bottom	★ ★ ★ ★ ★
Sides	★ ★ ★ ★ ★
Cutting edge	★ ★ ★ ★ ★
FRAME	
Play articulation point	★ ★ ★ ★ ★
Play loading frame	★ ★ ★ ★ ★
Play bucket pins	★ ★ ★ ★ ★
HYDRAULICS	
Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★ ★ ★ ★ ★
Hydraulic tank/sight glass and cap	★ ★ ★ ★ ★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★ ★ ★ ★ ★
BRAKE	
Brakelines	★ ★ ★ ★ ★
Service brake operation	★ ★ ★ ★ ★
Parking brake operation	★ ★ ★ ★ ★
Compressor	★ ★ ★ ★ ★
DRIVE TRAIN/TRANSMISSION	
Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
ELECTRICAL, STARTING AND CHARGING SYSTEM	
Alternator functioning	Yes
Wiring	★ ★ ★ ★ ★
Batteries	★ ★ ★ ★ ★

Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Beacon	Working

TYRES

FRONT LEFT

Tread dept in mm	175mm
Percentage life remaining	90%

REAR LEFT

Tread dept in mm	175mm
Percentage life remaining	90%

REAR RIGHT

Tread dept in mm	175mm
Percentage life remaining	90%

FRONT RIGHT

Tread dept in mm	175mm
Percentage life remaining	90%

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV

