

HAMM GRW15

Description

Hamm GRW15, Deutz , BF4M 2012 C, 88 kW, EPA, 11.00-20, Tyre regulation, Erops cabin, Water sprinkler system, Backup alarm, In very good and clean condition.



Year	2004
Hours	3146
Weight	11500 kg
Serial number	60123
Reference	210460

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

Copyright Smitma BV



INSPECTION REPORT

FEATURES

Engine brand	Deutz
Engine model	BF4M 2012 C
Engine power in kW	88 kW
EPA	✓
Tyre regulation	✓

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆☆
Decals	★★★★☆☆
Bonnet	★★★★☆☆
Engine cover doors	★★★★☆☆
Cabin	★★★★☆☆

ENGINE DETAILS AND CONDITION

Engine number	00805587
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-26°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆

Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★☆
Radiator	★★★★☆

SAFETY ITEMS

Backup alarm	Not Working
Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Heater	Not working
Gauges	Few don't work
Switches	★★★★☆
Warnings	No Warnings Available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Few don't work
Cabin floor	★★★★☆
Interior roof	★★★★☆
Seat	★★★★☆

TYRE REGULATION

Tyre regulation	Working
-----------------	---------

STEERING

Steering cylinders leaking	No
Play steering cylinders	★★★★☆

HYDRAULICS

Hydraulic lines and fittings	★★★★☆
Noise hydraulic pump normal	Yes
Operation condition hydraulics	★★★★☆

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Few lights don't work
Tail lights	Yes
Additional work lights working	Yes

FRONT TYRES

FIRST TYRE	
Percentage life remaining	60%
SECOND TYRE	
Percentage life remaining	60%
THIRD TYRE	
Percentage life remaining	60%
FOURTH TYRE	
Percentage life remaining	60%

REAR TYRES

FIRST TYRE	
Percentage life remaining	60%
SECOND TYRE	
Percentage life remaining	60%
THIRD TYRE	
Percentage life remaining	60%
FOURTH TYRE	
Percentage life remaining	60%

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

