

DYNAPAC CP224

Description

Dynapac CP224, Cummins , B3.3, 74kW, 13/80R20, Erops cabin, Water sprinkler system, Moveable seat, Speed meter, Air conditioning, Backup alarm, AM/FM radio, In very good and clean condition.



Year	2013
Hours	4349
Weight	21.900 kg
Serial number	10000501L0B003150
Reference	198995

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

Engine brand	Cummins
Engine model	B3.3
Engine power in kW	74kW

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Cabin	★★★★★

ENGINE DETAILS AND CONDITION

Air cleaner	Clean
Anti-freeze level °C	-26°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No

Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Air conditioning	Not Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warnings	No Warnings Available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

TYRE REGULATION

Tyre regulation	Not Working
-----------------	-------------

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Play articulating point	★★★★★
Steering cylinders leaking	No
Play steering cylinders	★★★★★

HYDRAULICS

Hydraulic level ok	Yes
--------------------	-----

Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operation condition hydraulics	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Few lights don't work
Tail lights	Few lights don't work

FRONT TYRES

FIRST TYRE	
Percentage life remaining	60%
SECOND TYRE	
Percentage life remaining	60%
THIRD TYRE	
Percentage life remaining	60%

REAR TYRES

FIRST TYRE	
Percentage life remaining	80%
SECOND TYRE	
Percentage life remaining	80%
THIRD TYRE	
Percentage life remaining	80%
FOURTH TYRE	
Percentage life remaining	80%

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

