

WIRTGEN WR200XLI

Description

Wirtgen WR200XLI, MTU (Mercedes), OM470, 320kW, CE, 620/75R26, Width of the milling drum 2.4m, Milling depth 500mm, Camera system, Backup alarm, Beacon, Air conditioning, Water sprayer, Genuine hours, In very good and clean condition.



Year	2016
Hours	7575
Weight	25.900 kg*
Serial number	09WR0040
Reference	209093

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine brand	MTU (Mercedes)
Engine model	OM470
Engine power in kW	320kW
EPA	✘
CE	✓
Hours	Genuine hours

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Cabin	★★★★★
All greasing points lubricated	Yes

ENGINE DETAILS AND CONDITION

Engine number	A470 051 02 02
Air cleaner	Clean
Anti-freeze level °C	-35°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★

Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No Warnings Available
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

DRUM

Toolholders	★★★★★
Picks	★★★★★
Scrapers	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Noise hydraulic pump normal	Yes

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes

SAFETY ITEMS

Backup alarm	Working
Backup camera	Working
Seat belt	Available

TYRES

FRONT LEFT	
Tread dept in cm	3cm
Percentage life remaining	60%
Retreaded	No
REAR LEFT	
Tread dept in cm	1cm
Percentage life remaining	20%
Retreaded	No
REAR RIGHT	
Tread dept in cm	3.5cm
Percentage life remaining	70%
Retreaded	No
FRONT RIGHT	
Tread dept in cm	4.5cm
Percentage life remaining	90%
Retreaded	No

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------

Copyright Smilma BV

