

VOLVO EWR150E - STABILIZERS

Description

Volvo EWR150E, Engine brand Volvo, D4J, 105kW, CE, Central lubrication, Backup camera, Backup alarm, Tyre size 315/80R22.5, V/A boom, Length of the stick 2.45m, Hydraulic quick release, Digging bucket with teeth, Width of the bucket 1.20m, Piped for hammer, Burst valve on lift, V/A and stick cylinder, In very good and very clean condition.



Year	2016
Hours	9590
Weight	18.400 kg
Serial number	VCEW150EV00320439
Reference	210695



[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine brand	Volvo
Engine Model	D4J
Engine power in kW	105kW
CE	✓
Tyre size	315/80R22.5
Boom	V/A boom
Bucket	Digging bucket with teeth
Width of the bucket	1.20m
Piped	Piped for hammer
Burst valve	Burst valve on lift, V/A and stick cylinder
Overall condition	In very good and very clean condition.

DOCUMENTS

CE document	✓
CE document	CE document available
Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Body work	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Chassis	★★★★☆
Counter weight	★★★★☆
Toolbox	★★★★☆
Steps/ladders	★★★★☆
Grab irons	★★★★☆
Cabin	★★★★☆
Cracks or welds	No

ENGINE DETAILS AND CONDITION

Engine number	11968401
Air cleaner	Clean
Anti-freeze level °C	-31°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★★☆☆
Engine supports	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆☆
Fan	★★★★☆☆
Radiator	★★★★☆☆

BUCKET

Overall condition of the bucket	★★★★☆☆
Bottom	★★★★☆☆
Sides	★★★★☆☆
Teeth	★★★★☆☆

SAFETY ITEMS

Backup alarm	Working
Backup camera	Working
Seat belt	Available
Horn	Working

OPERATOR STATION

Hourmeter	Working
-----------	---------

Air conditioning	Not Working
Heater	Not Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BOOM AND STICK

Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play boom pen	★★★★★
Play V/A boom pins	★★★★★
Play V/A cylinder	★★★★★
V/A cylinder leaking	No
Play stick cylinder	★★★★★
Stick cylinder leaking	No
Play stick pen	★★★★★
Play bucket cylinder	★★★★★

Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboom	★★★★★
Condition V/A boom	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional lights working	Few lights don't work

TYRES

FRONT LEFT	
Percentage life remaining	40%
REAR LEFT	
Percentage life remaining	30%
REAR RIGHT	
Percentage life remaining	30%
FRONT RIGHT	
Percentage life remaining	40%

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV