



## **CATERPILLAR 740 WATER TRUCK**

### Description

Caterpillar 740,: Engine Caterpillar, C15, Erops cabin, Air conditioning, 29.5R25, Retarder, Central lubrication, Backup camera, Hours certified by Caterpillar, In very good and clean condition



| Year          | 2005              |
|---------------|-------------------|
| Hours         | 14907             |
| Weight        | 35000             |
| Serial number | CAT00740JB1P00425 |
| Reference     | 206244            |









**Download photos** 

# CONTACT US: SALES@SMITMA.COM +31(0)773999840



# **INSPECTION REPORT**

| Brand                                      | Caterpillar           |
|--|-----------------------|
| Туре                                       | C15                   |
| Number                                     | LHX02004              |
| Arrangement number                         | 316-0602              |
| Coolant freeze resistance                  | -32°C                 |
| GENERAL                                    |                       |
| Hydraulic oil checked                      | ✓                     |
| Engine oil checked                         | ✓                     |
| Diesel checked                             | ✓                     |
| Transmission checked                       | ✓                     |
| Axles checked                              | ✓                     |
| Final drive checked                        | ✓                     |
| Transfer box checked                       | ✓                     |
| Air filter changed                         | ✓                     |
| MANUAL, BOOKS AND CE  Parts book           | <b>√</b>              |
| Operation manual                           | <b>/</b>              |
| MILEAGE                                    |                       |
| Kilometers shown on display                | 74935 km              |
| ENGINE                                     |                       |
| Blow by                                    | ****                  |
| Quality cooling liquid                     | Clear                 |
| Engine leakages                            | No leakages           |
| Remarks                                    | No remarks            |
| Engine overall condition                   | ****                  |
| HYDRAULICS                                 |                       |
|  | Fast enough           |
| Speed hydraulic functions                  | i ast chough          |
| Speed hydraulic functions  Hydraulic noise |                       |
|  | Normal<br>No leakages |

## **TRANSMISSION**

| Transmission   | All gears tested, shifts in order |
|--|-----------------------------------|
| BRAKES   |                                   |
| Brakes   | ****                              |
| BODY WORK  |                                   |
| Condition of the body work                                 | ****                              |
| Condition of the paint                                     | ****                              |
| CABIN  |                                   |
| Condition of the seat                                      | ****                              |
| Windows  | No cracks                         |
| Airconditioning  | Not working                       |
| CRACKS OR WELDS  |                                   |
| Cracks or welds  |                                   |
| GENERAL CONDITION  |                                   |
| General condition  | ****                              |
|  | ISTER                             |
| New/Excellent Very good Good Fair  ★★★★★ ★★★ ★ ★★★ ★ ★★★ ★ | Poor  ★ ★ ★ ★ ★                   |
|  | 19.00                             |