

## INSPECTION REPORT

### CATERPILLAR 908M | NEW TYRES

This Caterpillar 908M wheel loader is powered by the robust Caterpillar C3.3B engine, delivering 55kW of power. It features an Erops cabin for operator comfort, a hydraulic quick release system, and comes with a GP bucket with teeth and forks for versatile operations. The loader is equipped with a complete steering wheel and an immobilizer, ensuring security and ease of use. With hours certified by Caterpillar, this 2017 model is in very good and clean condition, making it a reliable choice for your construction needs.



## Specifications

Year	2017
Hours	3601
Weight	6500 kg
Serial number	CAT0908MCH8802134
Reference	212461

## Features

Engine and model	Caterpillar C3.3B
Engine power	55kW
CE	✓
Erops cabin	✓
Tyre size	405/70R20
Bucket	GP bucket with teeth
Width of the bucket	2.05m
Steering	Complete steering wheel
Hours	Hours certified by Caterpillar
Overall condition	In very good and clean condition.

## Documents

CE document	CE document available
Parts book	✓
Operation manual	✓

## General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★

## Engine Details And Condition

Engine number	8HG2952
Arrangement number	437-9054
Air cleaner	Clean
Anti-freeze level °C	-20°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

## Operator Station

Hourmeter	Working, hours certified by Caterpillar
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

## Bucket

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Teeth	★★★★★

## Frame

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

## Hydraulics

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

## Brake

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★

## Drive Train/ Transmission

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level front right final drive ok	Yes
Drivetrain leaks	No

## Electrical, Starting And Charging System

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

## Safety Items

Seat belt	Available
Horn	Working

## Tyres

### Front Left

Tread dept in mm	16mm
Percentage life remaining	100%
Retreaded	No

### Rear Left

Tread dept in mm	16mm
Percentage life remaining	100%
Retreaded	No

### Rear Right


Tread dept in mm	16mm
Percentage life remaining	100%
Retreaded	No

### Front Right

Tread dept in mm	16mm
Percentage life remaining	100%
Retreaded	No

 [+31 \(0\) 77 3999 840](tel:+31(0)773999840)

 [sales@smitma.com](mailto:sales@smitma.com)

 [+31 \(0\) 77 3999 840](https://wa.me/31773999840)