


LIEBHERR LR634

Description

Liebherr LR634, Engine Liebherr, D934L, 150kW, EPA, CE, Air conditioning, Erops cabin, GP bucket with teeth, Width of the bucket 2.50m, Backup camera, Backup alarm, Genuine hours, In good and clean condition.



Year	2008
Hours	8300
Weight	23.500 kg*
Serial number	VAUZ0992CZT009739
Reference	209445

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

Engine	Liebherr
Engine model	D934L
Engine power	150kW
EPA	✓
CE	✓
Erops cabin	✓
Bucket	GP bucket with teeth
Width of the bucket	2.50m
Hours	Genuine hours
Overall condition	In good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★ ★ ★ ★ ★
Decals	★ ★ ★ ★ ★
Bonnet	★ ★ ★ ★ ★
Engine cover doors	★ ★ ★ ★ ★
Chassis	★ ★ ★ ★ ★
Steps/ladders	★ ★ ★ ★ ★
Grab irons	★ ★ ★ ★ ★
Cabin	★ ★ ★ ★ ★
Pre-cleaner bowl	★ ★ ★ ★ ★
Toolbox	★ ★ ★ ★ ★

ENGINE DETAILS AND CONDITION

Engine number	2007 03 4144
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-28°C
Diesel anti-freeze added	Yes

Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	30%
Chains	30%
Bushings	30%
Sprockets	100%
Idlers	30%
Bottom rollers	20%
Top rollers	20%
Track pads	40%

OPERATOR STATION

Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Mirrors	Not broken

Note: One is missing

Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Teeth	★★★★★

FRAME

Play bucket pins	★★★★★
Cracks or welds	No

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Service brake operation	★★★★★
Parking brake operation	★★★★★

TRANSMISSION

Transmission oil level ok	Yes
Transmission noisy	No
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★

Cabin lights working

Few lights don't work

SAFETY ITEMS

Backup alarm	Working
Backup camera	Working
Seat belt	Available
Horn	Working

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★☆☆☆☆

Copyright Smitma BV

