

## KOBELCO SK500LC-9

### Description

Kobelco SK500LC-9, Engine brand and model Hino AA-P11C-VC, 271 kW, EPA, CE, Air conditioning, Central lubrication, Backup camera, Cabin protection, Cat walk, Width of the pads 900mm, Mono boom, Length of the mono boom 7.00m, Length of the stick 3.45m, Hydraulic quick release, Digging bucket with edge, Width of the bucket 2.03m, Piped for hammer & shear, Burst valve on lift and stick cylinder, AM/FM Radio, In good and clean condition.



Year	2014
Hours	12512
Weight	50.500 kg
Serial number	YS12-03539
Reference	207687

[Download photos](#)


CONTACT US:  
SALES@SMITMA.COM  
+31(0)773999840

New/Excellent  
★★★★★

Very good  
★★★★★

Good  
★★★★★

Fair  
★★★★★

Poor  
★★★★★


# INSPECTION REPORT

## FEATURES

Engine brand and model	Hino AA-P11C-VC
Engine power in kW	271 kW
EPA	EPA
CE	✓
Air conditioning	✓
Cabin protection	✓
Cat walk	✓
Width of the pads	900mm
Boom	Mono boom
Length of the mono boom	7.00m
Length of the stick	3.45m
Bucket	Digging bucket with edge
Width of the bucket	2.03m
Piped	Piped for hammer & shear
AM/FM Radio	✓
Overall condition	In good and clean condition.

## DOCUMENTS

Parts book	✓
Operation manual	✓

## GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆☆
Body work	★★★★☆☆
Decals	★★★★☆☆
Bonnet	★★★★☆☆
Engine cover doors	★★★★☆☆
Chassis	★★★★☆☆
Bottom plates	★★★★☆☆
Counter weight	★★★★☆☆
Toolbox	★★★★☆☆
Steps/ladders	★★★★☆☆

Grab irons	★★★★★
Cabin	★★★★★
Cracks or welds	Yes

## ENGINE DETAILS AND CONDITION

EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-21°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

## BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★

## UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	60%
Chains	80%

Bushings	80%
Sprockets	30%
Idlers	70%
Bottom rollers	50%
Top rollers	50%
Track pads	60%

## SAFETY ITEMS

Backup camera	Working
Seat belt	Available
Horn	Working

## OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

## HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No

Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

## BOOM AND STICK

Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play boom pen	★★★★★
Play stick cylinder	★★★★★
Stick cylinder leaking	No
Play stick pen	★★★★★
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboom	★★★★★
Condition stick	★★★★★

## SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

## ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Additional work lights working	Yes

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------

Copyright Smilma BV

