

CATERPILLAR 907M

Description

Caterpillar 907M , Engine and model Caterpillar C3.3B, 55kW, EPA, CE, Erops cabin, 405/70R18, Mitas, Hydraulic quick release, GP bucket with welded edge, Width of the bucket 2.02M, Forks, 3rd valve, Complete steering wheel, AM/FM radio, Hours certified by Caterpillar, In very good and very clean condition.



Year	2016
Hours	8167
Weight	5750 kg
Serial number	CAT0907MLH7700674
Reference	212227

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine and model	Caterpillar C3.3B
Engine power	55kW
EPA	EPA
CE	✓
Erops cabin	✓
Tyre size	405/70R18
Bucket	GP bucket with welded edge
Width of the bucket	2.02M
Steering	Complete steering wheel
Hours	Hours certified by Caterpillar
Overall condition	In very good and very clean condition.

DOCUMENTS

CE document	CE document available
Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Code immobilizer	715353
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Pre-cleaner bowl	★★★★★
Toolbox	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	8GC1984
Arrangement number	416-6088
EPA sticker available	Yes

Air cleaner	Clean
Anti-freeze level °C	-30°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★

FRAME

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level front right final drive ok	Yes
Drivetrain leaks	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Few lights don't work

SAFETY ITEMS

Seat belt	Available
Horn	Working

TYRES

FRONT LEFT

Tread dept in mm	15mm
Percentage life remaining	75%
Retreaded	No

REAR LEFT

Tread dept in mm	12mm
Percentage life remaining	60%
Retreaded	No

REAR RIGHT

Tread dept in mm	10mm
Percentage life remaining	50%
Retreaded	No

FRONT RIGHT

Tread dept in mm	11%
Percentage life remaining	55%
Retreaded	No

New/Excellent



Very good



Good



Fair



Poor

