

VOLVO A35E

Description

Volvo A35E, Engine Volvo, D12D, 280kW, Emission level Stage IIIA, CE, Air conditioning, 6x6, Erops cabin, 26,5 R25, Retarder, Big tailgate, Body extensions, Backup alarm, Genuine hours, In good and clean condition.



Year	2008
Hours	13567
Weight	28.500 kg
Serial number	A35EV10169
Reference	211969

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★★☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine	Volvo
Engine model	D12D
Engine power	280kW
Emission level	Stage IIIA
CE	✓
Air conditioning	✓
Configuration	6x6
Erops cabin	✓
Retarder	✓
Tailgate	Big tailgate
Backup alarm	✓
Hours	Genuine hours
Overall condition	In good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Chassis	★★★★☆
Steps/ladders	★★★★☆
Grab irons	★★★★☆
Cabin	★★★★☆
Transmission guard	★★★★☆
Pre-cleaner bowl	★★★★☆

ENGINE DETAILS AND CONDITION

Engine number	631156
Air cleaner	New
Anti-freeze level °C	-29 °C

Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

FRAME

Play front suspension frame	★★★★★
Play middle suspension frame	★★★★★

Play rear suspension frame	★★★★★
Play articulation point	★★★★★
Shock absorbers articulation point	★★★★★
Play body tipping pin	★★★★★
Bearings tipping cylinders	★★★★★
Shock absorbers body	★★★★★
Play rear equalizer	★★★★★
Shock absorbers equalizer	★★★★★
Cracks or welds	Yes

BODY

Condition outside body	★★★★★
Body plates	★★★★★
Condition tailgate	★★★★★
Cracks or welds	Yes

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★
Brake pedal	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Differential lock/unlock working	Yes
Oil level front axle ok	Yes
Oil level middle axle ok	Yes
Oil level rear axle ok	Yes

Drive chain leaks	No
-------------------	----

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Few lights don't work
Tail lights working	Few lights don't work

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working

TYRES

FRONT LEFT

Tread dept in mm	38mm
Percentage life remaining	90%
Retreaded	No

MIDDLE LEFT

Tread dept in mm	8mm
Percentage life remaining	15%
Retreaded	No

REAR LEFT

Tread dept in mm	19mm
Percentage life remaining	50%
Retreaded	No

REAR RIGHT

Tread dept in mm	25mm
Percentage life remaining	70%
Retreaded	No

MIDDLE RIGHT

Tread dept in mm	30mm
------------------	------

Percentage life remaining 75%

Retreaded No

FRONT RIGHT

Tread dept in mm 8mm

Percentage life remaining 15%

Retreaded No

New/Excellent



Very good



Good



Fair



Poor

