

CATERPILLAR 972 14A | 4400H IDLE TIME! ORIGINAL PAINT!

Description

Caterpillar 972 14A, Engine and model Caterpillar C9.3B, 239kW, CE, Emission level Stage V, Air conditioning, Erops cabin, 26,5 R25, GP bucket with welded edge, Width of the bucket 3.03m, Joy stick control, Ride control, Autoshift, Backup camera, Backup alarm, Cental lubrication available but not tested, Immobilizer, Beacon, AM/FM radio, Hours certified by Caterpillar, 4400 IDLE TIME! ORIGINAL PAINT!, In very good and very clean condition.



Year	2023
Hours	9963
Weight	24.900 kg
Serial number	CAT00972PWF900526
Reference	211607

Download photos



CONTACT US:
 SALES@SMITMA.COM
 +31(0)773999840

New/Excellent
 ★★★★★

Very good
 ★★★★★★

Good
 ★★★★★★

Fair
 ★★★★★★

Poor
 ★★★★★★



INSPECTION REPORT

FEATURES

Engine and model	Caterpillar C9.3B
Engine power	239kW
CE	✓
Emission level	Stage V
Erops cabin	✓
Tyre size	26,5 R25
Bucket	GP bucket with welded edge
Width of the bucket	3.03m
Steering	Joy stick control
Ride control	✓
Autoshift	✓
Central lubrication	Cental lubrication available but not tested
Beacon	✓
Hours	Hours certified by Caterpillar
Overall condition	In very good and very clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Code immobilizer	0526
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Pre-cleaner bowl	★★★★★
Toolbox	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	XWE21811
Arrangement number	563-1249
Air cleaner	Clean
Anti-freeze level °C	-32°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working

Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★

FRAME

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
Drivetrain leaks	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Beacon	Working

TYRES

FRONT LEFT

Percentage life remaining	100%
Retreaded	No

REAR LEFT

Percentage life remaining	100%
Retreaded	No

REAR RIGHT

Percentage life remaining	100%
Retreaded	No

FRONT RIGHT

Percentage life remaining	100%
Retreaded	No

New/Excellent



Very good



Good



Fair



Poor

