

HAMM DV90 VO

Description

Hamm DV90, Deutz , TCD L04, 74,9kW, Width of the drum 1,66m, EPA, CE, Erops cabin, Water sprinkler system, Both drum vibrating, Oscillation compaction, Compaction frequency variable controllable , Splitted drum, Cutting edge, Moveable seat, Frequency meter, Speed meter, Backup alarm, Beacon, AM/FM radio, Genuine hours, In good and clean condition.



Year	2009
Hours	6101
Weight	9.410 kg
Serial number	H1920054
Reference	211075

[Download photos](#)

CONTACT US:

SALES@SMITMA.COM

+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★



INSPECTION REPORT

FEATURES

Engine brand	Deutz
Engine model	TCD L04
Engine power in kW	74,9kW
EPA	✓
CE	✓

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Decals	★★★★★
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Chassis	★★★★☆
Steps/ladders	★★★★☆
Cabin	★★★★☆

ENGINE DETAILS AND CONDITION

Engine number	10782859
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-28°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★☆
Exhaust stack	★★★★★
Hoses	★★★★★
Good cold start	Yes

Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

SAFETY ITEMS

Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Heater	Not Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Not Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

FRONT DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Travel motors	★★★★★
Left final drive leaking	Not Major
Vibration	High and low vibration frequency working

Drum measured in mm

20mm

REAR DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Travel motors	★★★★★

Drum measured in mm

20mm

STEERING

Steering cylinders leaking	No
Play steering cylinders	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Few lights don't work
Tail lights working	Few lights don't work
Additional lights working	Few lights don't work

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

Copyright Smitma BV

