

DYNAPAC CA6500D

Description

Dynapac CA6500D, Deutz , TCD 2012 L06 2V, 150 kW, Erops cabin, 23.1R26, Compaction meter, Frequency meter, Speed meter, Air conditioning, Backup alarm, Beacon, AM/FM radio, In very good and clean condition.



Year	2012
Hours	4679
Weight	20610 kg
Serial number	10000136C0A010366
Reference	207654

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine brand	Deutz
Engine model	TCD 2012 L06 2V
Engine power in kW	150 kW
Tyre size	23.1R26
Speed meter	✓
Beacon	✓
Overall condition	In very good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Steps/ladders	★★★★★
Cabin	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	11269421
Air cleaner	New
Anti-freeze level °C	-27°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★

Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Parking brake	Working
Beacon	Working

OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warnings	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Not Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★

Drum scrapers	★★★★★
Leakages	No
Drum oil level ok	Yes
Vibration	High and low vibration frequency working

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Play articulating point	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

DRIVE CHAIN

Rear axle leakages	No
Wheel bolts and rims	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

TYRES

REAR LEFT TYRES	
Tread dept in mm	7mm
Percentage life remaining	30%

REAR RIGHT TYRES

Tread dept in mm	9mm
Percentage life remaining	40%

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

Copyright Smitma BV

