

INSPECTION REPORT

CATERPILLAR 907H

The Caterpillar 907H is a robust and efficient wheel loader, equipped with a Caterpillar C3.4 engine that provides 55kW of power, compliant with CE and Tier 3 emission standards. The machine features an Erops cabin, 405/70R18 tires, hydraulic quick release, and a versatile GP bucket with a bolt-on edge, measuring 2.10m in width. Additionally, it includes forks, a third valve, and a complete steering wheel. Certified Caterpillar hours ensure reliability. This 2011 model, originating from the United Kingdom, is in excellent and clean condition with only 4,786 operating hours.



Specifications

Year	2011
Hours	4786
Weight	6000
Serial number	CAT0907HCSJM00545
Reference	212460

Features

Engine and model	Caterpillar C3.4
Engine power	55kW
CE	✓
Emission level	Tier 3
Erops cabin	✓
Tyre size	405/70R18
Bucket	GP bucket with bolt on edge
Width of the bucket	2.10m
Steering	Complete steering wheel
Hours	Hours certified by Caterpillar
Overall condition	In good and very clean condition.

Documents

CE document	CE document available
Parts book	✓
Operation manual	✓

General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★

Engine Details And Condition

Engine number	CYM23814
Arrangement number	305-2571
Air cleaner	Clean
Anti-freeze level °C	-20°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

Operator Station

Hourmeter	Working, hours certified by Caterpillar
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

Bucket

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★

Frame

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

Hydraulics

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

Brake

Service brake operation	★★★★★
Parking brake operation	★★★★★

Drive Train/ Transmission

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level front right final drive ok	Yes
Drivetrain leaks	No

Electrical, Starting And Charging System

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★☆
Starter	★★★★☆
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

Safety Items

Seat belt	Available
-----------	-----------

Tyres

Front Left

Tread dept in mm	11mm
Percentage life remaining	50%
Retreaded	No

Rear Left


Tread dept in mm	14mm
Percentage life remaining	70%
Retreaded	No

Rear Right


Tread dept in mm	11mm
Percentage life remaining	50%
Retreaded	No

Front Right

Tread dept in mm	10mm
Percentage life remaining	50%
Retreaded	No

 [+31 \(0\) 77 3999 840](tel:+31(0)773999840)

 sales@smitma.com

 [+31 \(0\) 77 3999 840](https://wa.me/31773999840)