

VOGELE SUPER 1800-3I

Description

Vogele super 1800-3I, Engine brand Cummins, QSB6, 130 kW, EPA, Track driven, 23AB / AB 500-3 TV, 5.00m , Tamping & vibrating function, Electrical heated, Hydraulic crown adjustment, Vogele level control, 2 grade & 1 slope control, Hard cover roof, Central lubrication, Genuine hours, NEW PADS, In very good and clean condition



Year	2015
Hours	10759
Weight	19.400 kg
Serial number	14820623
Reference	208990

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

Copyright Smitma BV



INSPECTION REPORT

FEATURES

Engine brand	Cummins
Engine model	QSB6
Engine power in kW	130 kW
EPA	✓
Track driven	✓
Screed model	23AB / AB 500-3 TV
Width of the screed	5.00m
Screed function	Tamping & vibrating function
Screed heating	Electrical heated
Hydraulic side plates	✗
Hydraulic crown adjustment	✓
Brand high leveling	Vogele level control
Roof	Hard cover roof
Central lubrication	✓
Hours	Genuine hours
Overall condition	In very good and clean condition

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Central greasing working	Yes
Cracks or welds	No

Condition of the hopper plates in mm	9mm
Condition of the hopper	★★★★★
Condition of the augers	★★★★★
Condition of the screed plates in mm	9mm

ENGINE DETAILS AND CONDITION

Engine number	22132317
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-19°C
Diesel anti-freeze	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	70%
Track pads	100%
Track chains and sprockets	70%

OPERATOR STATION

Hourmeter	Working
Gauges	Working

Switches	★★★★★
Display	★★★★★
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Seat	★★★★★

HYDRAULICS

Hydraulic oil level	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	No
Operating condition hydraulics	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission oil level ok	Yes
Transmission noisy	No
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Drivetrain leaks	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes

SAFETY ITEMS

Backup alarm	Working
Horn	Working

GEARBOX

Gearbox worms checked	Yes
Gearbox pumps checked	Yes
Gearbox conveyor checked	Yes

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------

Copyright Smilma BV

