

VOGELE SUPER 1800-2

Description

Vögele 1800-2, Engine brand Perkins, 1106DE66TA, 129.5, EPA, CE, Track driven, 15Ab/Ab500-2TP1, 500, Tamping & high compaction function, Electrical heated, Hydraulic crown adjustment, Vögele level control, 2 grade & 1 slope control, Hard cover roof, Central lubrication, Genuine hours, In good and clean condition



| | |
|---------------|------------|
| Year | 2007 |
| Hours | 7835 |
| Weight | 19.300 kg* |
| Serial number | 11820156 |
| Reference | 206962 |

[Download photos](#)



CONTACT US:
 SALES@SMITMA.COM
 +31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

| | |
|----------------------------|------------------------------------|
| Engine brand | Perkins |
| Engine model | 1106DE66TA |
| Engine power in kW | 129.5 |
| EPA | ✓ |
| CE | ✓ |
| Track driven | ✓ |
| Screed model | 15Ab/Ab500-2TP1 |
| Width of the screed | 500 |
| Screed function | Tamping & high compaction function |
| Screed heating | Electrical heated |
| Hydraulic side plates | ✘ |
| Hydraulic crown adjustment | ✓ |
| Brand high leveling | Vogele level control |
| Roof | Hard cover roof |
| Central lubrication | ✓ |
| Hours | Genuine hours |
| Overall condition | In good and clean condition |

DOCUMENTS

| | |
|------------------|---|
| Parts book | ✓ |
| Operation manual | ✓ |

GENERAL APPEARANCE

| | |
|-------------------------------|-------|
| Stamped serial number checked | Yes |
| Serial number plate checked | Yes |
| Paint | ★★★★☆ |
| Body work | ★★★★☆ |
| Decals | ★★★★☆ |
| Bonnet | ★★★★☆ |
| Engine cover doors | ★★★★☆ |
| Chassis | ★★★★☆ |
| Steps/ladders | ★★★★☆ |
| Grab irons | ★★★★☆ |
| Cabin | ★★★★☆ |
| Pre-cleaner bowl | ★★★★☆ |

| | |
|--------------------------------------|-------|
| Central greasing working | Yes |
| Cracks or welds | Yes |
| Condition of the hopper plates in mm | 8 |
| Condition of the hopper | ★★★★☆ |
| Condition of the augers | ★★★★☆ |
| Condition of the screed plates in mm | 11 |

ENGINE DETAILS AND CONDITION

| | |
|-----------------------------|---------|
| Engine number | PJ38510 |
| EPA sticker available | Yes |
| Air cleaner | Clean |
| Anti-freeze level °C | -36 |
| Diesel anti-freeze | Yes |
| Diesel level ok | Yes |
| Cooling liquid level ok | Yes |
| Engine oil level ok | Yes |
| Exhaust manifold | ★★★★☆ |
| Muffler | ★★★★☆ |
| Exhaust stack | ★★★★☆ |
| Engine supports | ★★★★☆ |
| Hoses | ★★★★☆ |
| Good cold start | Yes |
| Engine power | ★★★★☆ |
| Blow by | ★★★★☆ |
| Knocking | No |
| Compression in the radiator | No |
| Water in the oil | No |
| Oil in the water | No |
| Smoke | Normal |
| Engine leaks | No |
| Belts and pulleys | ★★★★☆ |
| Fan | ★★★★☆ |
| Radiator | ★★★★☆ |

UNDERCARRIAGE LEFT IN LIFE IN %

| | |
|----------------------------|----|
| Overall condition | 90 |
| Track pads | 90 |
| Track chains and sprockets | 90 |

OPERATOR STATION

| | |
|-----------|-----------------------|
| Hourmeter | Working |
| Gauges | Working |
| Switches | ★★★★☆ |
| Display | ★★★★☆ |
| Warning | No warnings available |
| Seat | ★★★★☆ |

HYDRAULICS

| | |
|------------------------------------|-------|
| Hydraulic oil level | Yes |
| Hydraulic lines and fittings | ★★★★☆ |
| Hydraulic tank/sight glass and cap | ★★★★☆ |
| Hydraulic valves leaking | No |
| Noise hydraulic pump normal | No |
| Operating condition hydraulics | ★★★★☆ |

DRIVE TRAIN/TRANSMISSION

| | |
|-------------------------------------|-----|
| Transmission oil level ok | Yes |
| Transmission noisy | No |
| Oil level rear left final drive ok | Yes |
| Oil level rear right final drive ok | Yes |
| Drivetrain leaks | No |

ELECTRICAL, STARTING AND CHARGING SYSTEM

| | |
|------------------------|-------|
| Alternator functioning | Yes |
| Wiring | ★★★★☆ |
| Batteries | ★★★★☆ |
| Starter | ★★★★☆ |
| Cabin lights working | Yes |

SAFETY ITEMS

| | |
|------|---------|
| Horn | Working |
|------|---------|

GEARBOX

| | |
|--------------------------|-----|
| Gearbox worms checked | Yes |
| Gearbox pumps checked | Yes |
| Gearbox conveyor checked | Yes |

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV