



INSPECTION REPORT

VOLVO A30F



Specifications

Year	2012
Hours	14687
Weight	23.200 kg
Serial number	VCE0A30FC00012382
Reference	204699

Features

Engine	Volvo
Engine model	D11H
Engine power	265 kW
CE	✓
Air conditioning	✓
Configuration	6x6
Erops cabin	✓
Retarder	✓
Tailgate	Big tailgate
Backup camera	✓
Backup alarm	✓
Overall condition	In very good and clean condition.

Documents

Parts book	✓
Operation manual	✓

General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Transmission guard	★★★★★

Engine Details And Condition

Engine number	263346
Air cleaner	New
Anti-freeze level °C	-24°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

Operator Station

Hourmeter	Working
Total kilometers	115974 km
Air conditioning	Not working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Small crack no need to repair
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

Frame

Play front suspension frame	★★★★★
Play middle suspension frame	★★★★★
Play rear suspension frame	★★★★★
Play articulation point	★★★★★
Shock absorbers articulation point	★★★★★
Play body tipping pin	★★★★★
Bearings tipping cylinders	★★★★★
Shock absorbers body	★★★★★
Play rear equalizer	★★★★★
Shock absorbers equalizer	★★★★★
Cracks or welds	No

Body

Condition outside body	★★★★★
Body plates	★★★★★
Condition tailgate	★★★★★
Cracks or welds	Yes

Hydraulics

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

Brake

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★
Brake pedal	★★★★★

Drive Train/ Transmission

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transfer gear box oil level ok	Yes
Transmission noisy	No
Differential lock/unlock working	Yes
Oil level front axle ok	Yes
Oil level middle axle ok	Yes
Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level middle left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level middle right final drive ok	Yes
Oil level front right final drive ok	Yes
Drive chain leaks	No

Electrical, Starting And Charging System

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes

Safety Items

Backup alarm	Working
Backup camera	Not working
Seat belt	Available
Horn	Working

Tyres

Front Left

Tread dept in mm	29mm
Percentage life remaining	70%

Middle Left

Tread dept in mm	16mm
Percentage life remaining	40%
Retreaded	Yes

Rear Left

Tread dept in mm	14mm
Percentage life remaining	30%
Retreaded	Yes

Rear Right

Tread dept in mm	13mm
Percentage life remaining	20%
Retreaded	Yes

Middle Right

Tread dept in mm	10mm
Percentage life remaining	10%
Retreaded	Yes

Front Right

Tread dept in mm	30mm
Percentage life remaining	70%



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)



sales@smitma.com



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)