

Komatsu, 855.1 - Forwarder
Komatsu - Inspection report

Images



Information

Brand: **Komatsu**
Model: **855.1**
Serial number: **8550011187**
Country: **France**
Model year: **2015**

Year of manufacture: **2015**
Reg.nr: **2024-4332**
Hours when delivery: **15 500**
Location: **Egletons**

Base machine

Front axle: **Boogie**
Automatic sprinkler: **Yes**
Extinguishing: **Installed, Approved**
Bogie lift: **No**
Front blade: **Yes**
Paintwork: **Good**

Rear axle: **Boogie**
Ladder: **Fair**
Central lubrication: **Yes**
Gear box: **Good** *changé à 12 000 h*
Bull bar: **No**
Hydrostatic: **OK**

Tyres

Left-front-front: **50%**
Left-front-back: **50%**
Left-back-front: **50%**
Left-back-back: **50%**
Brand front: **Nokian**
Front dimensions: **600x26,5**

Right-front-front: **50%**
Right-front-back: **50%**
Right-back-front: **50%**
Right-back-back: **50%**
Brand back: **Nokian**
Back dimensions: **600x26,5**



Diesel engine

Cooling system: **Good**
Electric system: **Good**
Adblue: **Working**

Heatingloop in hydraulic tank: **Yes**
Electric pump: **Yes**
Diesel heater: **Good**



Hydraulics

Hydraulic system: **Good**
Pump: **Good**
Hydraulic oil: **Komatsu HE GEN II Natura**

Density: **OK**
Valve bank: **Good**
Other options: **Vacuum pump & hydraulic filling pump**

Cabin

Seat type: **3000 BeGe**
Crane lever: **Good**
Control system: **MaxiXplorer**
Work lights: **LED**
Transport lights: **Yes**
Air condition: **Good**
Platform: **OK**
Service ladder: **OK**
User manual: **Yes**
Parts book: **Yes**


Seat condition: **Fair**
Crane lever: **Mini**
Operation monitoring: **Yes**
Windshield: **Good**
Wipers: **Front & Back**
Sun curtains: **Fair**
Radio: **Radio**
Rearview cam: **Good**
Machine folder: **Yes**
Comments: *2 écrans de contrôle*



Crane

Crane: **Good**
Length (m): **7.80 m**
Slew house: **Good**
Rotator: **Fair**
Condition: **Fair**
Crane lights: **Yes**
Crane damper: **No**
Slewing unit: **Good**

Model: **CRF 12**
Boom system: **Good calage télescope**
Link: **Double braked, Good**
Grapple: **Komatsu**
Size: **G 36**
Crane lights condition: **Fair**
Tilt plate: **Good condition**



Load carriers

Bunks: **ALS, Fair**
Head board: **Raiseable, Fair**

Quantity: **4**
Frame: **Extended before bogie**



Other

Other: **lame avant**



Overall evaluation condition